

## CERTIFICATION PROGRAMS

### 2010 HPVA Certification and Laboratory Testing Services Price List

*Effective January 1, 2010*

<u>Service</u>	<u>Member</u>	<u>Non-Member</u>
<b>CERTIFICATION PROGRAM (ISO 65)-Annual</b>		
Initial Program:* (pick one)	\$4,500	\$5,500
CARB-TPC-8;		
ANSI/HPVA HP-1 and EF:		
HUD;		
KCMA;		
FIRE		
Lacey Due Diligence		
*Add another certification program and save	\$2,500	\$3,500
<b>MILL INSPECTION FEE (per visit)**</b>	<b>\$400*</b>	<b>\$500*</b>
** Additional mileage and service fee for facilities outside normal zones		
<b>Inspection fee for each additional certification program</b>	<b>\$225</b>	<b>\$275</b>
<b>Re-INSPECTION FEE (per visit)*</b>	<b>\$400*</b>	<b>\$500*</b>
<b>ANNUAL AUDIT and QC Review**</b>	<b>\$300*</b>	<b>\$350*</b>
** Plus travel expenses		
<b>Primary Data set ASTM E1333 LSC Correlation</b>	<i>Custom Quote</i>	<i>Custom Quote</i>
	\$2,620/ est.	\$3,600/est.
	per prdt.line	per prdt.line
<b>HCHO Training</b>	<i>Custom quote</i>	<i>Custom quote</i>
<b>QC Testing Program</b>	<i>Custom quote</i>	<i>Custom quote</i>

<u>Service: Formaldehyde Tests</u>	<u>Member</u>		<u>Non-Member</u>	
	Reston	West Lab	Reston	West Lab
<b>ASTM E 1333 (LSC)</b>	\$400	\$650	\$500	\$750
Panels	\$400	\$650	\$480	\$750
Doors	\$550	N/A	\$660	N/A
Finished EWF	\$700	N/A	\$840	N/A
Furniture/Cabinets	\$400	N/A	\$480	N/A
Rush Surcharge	\$130	\$150	\$130	\$150
<b>ASTM D 5582-94 (desiccator)</b>	\$54	N/A	\$70	N/A
<b>ASTM D 6007 (true small scale chamber) (0.7 m<sup>3</sup> chamber)</b>				
Certification	\$250	\$650	\$350	\$750
Q/C	\$100		\$125	
<b>DNPH Test Analysis</b>	\$150	\$45	\$180	\$55
<b>Dosimeter (3-M badge)</b>	\$75	N/A	\$90	N/A

## FIRE TESTING

### Service: Fire and Smoke Testing - Reston, VA facility

#### ASTM E 84 - Tunnel

##### Surface burning characteristics

One Burn \$575

One test for fire treated wood \$950

##### Mounting Fees:

Cement board w/ Sairmix#7 \$185

Cement board w/Kentile#9 Epoxy \$225

Gypsum board (5/8" type X) \$150

Rods \$25

Rods and wire \$75

Steel bars \$150

Lid extension \$125

Special clean-up for plastics or excessive melt \$300

Flame spread certification test program - one burn \$475

#### ASTM E 162 - Radiant Panel

Flame spread Index Determination \$455

#### ASTM E 662 - Smoke Box

Smoke determinations \$425

#### ASTM E 648 - Radiant Heat Source

Critical radiant flux of floor coverings systems \$400

#### Motor Vehicle Safety Standard no. 302

Flamability: MVSS, Federal Highway Administration, DOT \$125

-  
**Shear tests to meet the requirements  
of ANSI/HPVA HP-1 2004 ( Type I and Technical Type)**

	<u>Member</u>	<u>Non-Member</u>
<b>Dry Shear (minimum fee)</b>	\$350	\$390
3-Ply Plywod (6 shear specimens)	\$70	\$80
5 or more Ply Plywood (12 specimens)	\$140	\$155

**Full set of 10 Panels**

**3 samples per panel** from the same lot (ANSI/HPVA HP-1 2004)

<b>3-ply plywood (180 shear specimens)</b>	\$1,400	\$1,550
<b>5-ply or more plywood (360 specimens)</b>	\$2,800	\$3,100

<b>Cyclic Boil Test (minimum fee)</b>	\$350	\$390
3-Ply Plywood (6 shear specimens)	\$70	\$80
5 of more ply plywood (12 specimens)	\$140	\$155

**Full set of 10 Panels**

**3 samples per panel** from the same lot (ANSI/HPVA HP-1 2004)

<b>3-ply plywood (180 shear samples)</b>	1,400	1,550
<b>5-ply or more plywood (360 specimens)</b>	2,800	3,100

**Two-Cycle Boil Test**

ANSI/HPVA HP-1 2004 Type I

<b>Per test of ten(10) panels</b>	\$240	\$270
-----------------------------------	-------	-------

**Three- Cycle Boil Test**

ANSI/HPVA HP-1 2004 Type II

<b>Per test of ten (10) panels</b>	\$190	\$210
------------------------------------	-------	-------

**3 Cycle Soak-Dry Type II Bond Test**

ANSI/HPVA EF 2002 & ANSI/HPVA HP-1

<b>Per test of ten (10) blocks or less</b>	\$160	\$180
--	-------	-------

<b>Moisture Content</b>	\$160	\$180
-------------------------	-------	-------

## OTHER SERVICES

### *Services:*

#### **Additional Reports**

Extra copies of printed reports	\$10/per copy
Re-issue printed report with changes	\$100/test report
Re-issue archived reports without changes	\$50/per report

#### **Inspection and Miscellaneous Laboratory fees:**

Re-inspection plywood facility, technical testimony in legal proceedings, or advisory services	
Members:	\$650 per diem plus travel and direct expenses
Non-members:	\$800 per diem plus travel and direct expenses

Miscealleneous services to evaluate defective products (one hour minimum)

Members:	\$80/ hour
Non-members:	\$105/hour

***Cutting fee for HPVA to produce samples for product testing: Minimum fee \$50 for ASTM D5582-94 and and E 84 up to \$100 for E 1333***

**ALL FREIGHT CHARGES MUST BE PRE-PAID BY THE SHIPPER**

***HPVA WILL ASSESS a \$50 HANDLING FEE FOR COLLECT FREIGHT***

### **SPECIAL PROGRAMS**

***Trust But Verify*** - call for special quote

For fabricators, importers of record, and distributors

***CARB-Lite for Fabricators*** - call for special quote

For fabricators laminating face veneers